


1



2



Ax1



Bx1



Cx1




Dx4



M6x16

Ex2



M6x30

Fx4



Gx1

